



## VFDSOft Installation

Install the VFDSOft USB driver execution file manually step by step:


Step 1: Download and install the latest version of VFDSOft which is compatible to V1.542 and above.

Download link:



Step 2: Open the file browser, and enter the installation path of VFDSOft.


Installation path: C: > Program Files (x86) > Delta Industrial Automation > AC Motor Drive > VFDSOft > DeltaDriver



Step 3: Choose your OS version.

x86 (32 bit): Proceed to Step 3.1

x64 (64 bit): Proceed to Step 3.2





Step 3.1: Choose x86 and execute `dpinst.exe`. Ignore all warning messages and click “YES” till the end.

	CDC_Demo.inf	2016/8/31 上午 1...	安裝資訊	2 KB
	CDC_Demo_Win7.inf	2016/8/31 上午 0...	安裝資訊	3 KB
	CDC_Demo_Win7_sh.inf	2016/8/31 上午 1...	安裝資訊	3 KB
	dpinst.exe	2008/8/26 下午 0...	應用程式	538 KB
	serenum.sys	2008/4/15 下午 0...	系統檔案	16 KB
	silabenm.sys	2014/4/12 上午 0...	系統檔案	16 KB
	silabser.sys	2014/4/12 上午 0...	系統檔案	67 KB
	slabvcp.cat	2014/4/12 上午 0...	安全性目錄	12 KB
	slabvcp.inf	2014/4/12 上午 0...	安裝資訊	5 KB
	usbser.sys	2008/4/14 上午 1...	系統檔案	26 KB

Step 3.2: Choose x64 and execute `dpinst64.exe`. Ignore all warning messages and click “YES” till the end.

	CDC_Demo.inf	2016/8/31 上午 1...	安裝資訊	2 KB
	CDC_Demo_Win7.inf	2016/8/31 上午 0...	安裝資訊	3 KB
	CDC_Demo_Win7_sh.inf	2016/8/31 上午 1...	安裝資訊	3 KB
	dpinst64.exe	2014/12/14 下午 ...	應用程式	1,023 KB
	serenum.sys	2008/4/15 下午 0...	系統檔案	16 KB
	silabenm.sys	2014/4/12 上午 0...	系統檔案	23 KB
	silabser.sys	2014/4/12 上午 0...	系統檔案	78 KB
	slabvcp.cat	2014/4/12 上午 0...	安全性目錄	12 KB
	slabvcp.inf	2014/4/12 上午 0...	安裝資訊	5 KB
	usbser.sys	2008/4/14 上午 1...	系統檔案	26 KB

Step 4: Connect AC motor drive to the computer, then open Device Manager to check if the USB COM Port is now “CDC USB Demonstration”.

